


EUROQUARTZ GROUP OBSOLESCENCE NOTIFICATION

SUMMARY			
PRODUCT CODE	XOE32, XOE53 and XOE91 Series	ADVICE NUMBER	000030
SPECIFICATION	±1ppm tolerance, ±5ppm over -10° to +70°C Tight tolerance clock oscillator.		
REASON FOR OBSOLESCENCE	The chipset was unable to hold the stability required in conjunction with the crystal. The part was out of specified limits after short periods of time.		
CUSTOMER	All		
Raised By	Andy Treble	Date Raised	11 th Jan 2017
Amended			
Authorised By	Andy Treble – Quality Manager	Telephone	01460 230000
DETAILS OF OBSOLESCENCE			
The above ranges of product has been obsoleted due inability to produce to specifications due to chipset issues.			
ALTERNATIVE PARTS			
XOR series are a close functional replacement			
LAST TIME BUY DETAILS			
<u>None</u>			
Authorised Signature		Date	11th January 2017